

HERBERT METZENDORFF & CO. KG

Hohe-Schaar-Strasse 47 - 21107 Hamburg
www.metzendorff-co.com



METZENDORFF

HERBERT METZENDORFF & CO. KG - Hohe-Schaar-Strasse 47 - 21107 Hamburg

Stock list

Hamburg **November 16th, 2012**

Stock list Herbert Metzendorff & Co. KG

Description	Part number	Engine	Qty	Condition
Diffusor	000 096 0067 0000960067	MTU 839	2	New
Driving Dog	000 187 0059 0001870059	MTU 839	3	New
Cooler Insert	000 188 0310 0001880310	MTU 839	1	New
Circulation Pump	000 201 4000 0002014000	MTU 839	1	New
Solenoid	001 203 4275 0012034275	MTU 839	6	New
Injection Pump, old Design	002 074 0101 0020740101	MTU 839	8	New
Conrod Bearing, Inner	112 B10 704-2 112B107042	MTU 839	22	New
Bracket	112 E50 706-1 112E507061	MTU 839	4	New
Main Bearing, Rep. 1	114 B99 745-3 114B997453	MTU 839	16	New
Thrust Bearing	114 B99 752-4 114B997524	MTU 839	1	New
Distance Washer	114 C04 067-1 114C040671	MTU 839	10	New
Drain Plug R3/4"-St-Sw14	114 F36 001-1 114F360011	MTU 839	1	New
Bearing Flange	114 K03 702-1 114K037021	MTU 839	2	New
Washer	114 L49 015-1 114L490151	MTU 839	15	New
Valve Housing	114 L89 502-1 114L895021	MTU 839	1	New
Valve Housing	114 L89 505-1 114L895051	MTU 839	3	New
Injection Line, B1-8	114 M09 701-2 114M097012	MTU 839	1	New
Fuel Leak-Off Line	114 M12 701-1 114M127011	MTU 839	5	New
Adapter	114 M37 501-1 114M375011	MTU 839	8	New



Contact	Bank account	Manager & Owner	Chamber of Commerce
Tel: +49 (40) 75 60 59 -0 Fax: +49 (40) 75 95 62 info@metzendorff-co.de TraderNet-ID: 67486	Deutsche Bank AG, Hamburg BIC-No.: DEUTDE33HAN IBAN-No.: DE87 2007 0024 0240 0000 00	Jörn Johannsen Hinrich Warnecke Torben Johannsen	Hamburg registered under A 32 251 VAT-Id.: DE 118 258 306

Description	Part number	Engine	Qty	Condition
Terminal Box	114 M37 704-1 114M377041	MTU 839	2	New
Charge Air Manifold	114 M37 713-2 114M377132	MTU 839	2	New
Bracket	114 M64 703-1 114M647031	MTU 839	3	New
Bracket	114 M64 712-1 114M647121	MTU 839	60	New
Drain Pipe	114 P31 701-1 114P317011	MTU 839	3	New
Drain Plug R3/4"-St-Sw14	132 M48 019-1 132M480191	MTU 839	6	New
Intermediate Plate	133 D06 701-2 133D067012	MTU 839	5	New
Start Adjuster	134 L67 701-1 134L677011	MTU 839	7	New
Connecting Pipe	135 A03 016-1 135A030161	MTU 839	2	New
Spacer Bush	135 A32 006-1 135A320061	MTU 839	5	New
Valve Clamp	135 A48 509-1 135A485091	MTU 839	2	New
Screw	135 B02 004-1 135B020041	MTU 839	9	New
Screw	135 B02 007-1 135B020071	MTU 839	10	New
Nut, Special	135 B02 012-1 135B020121	MTU 839	20	New
Dowel Pin	135 B09 007-2 135B090072	MTU 839	69	New
Dowel Pin	135 B09 008-1 135B090081	MTU 839	84	New
Conrod Bearing, Fork, Rep. 5	135 B99 707-5 135B997075	MTU 839	6	New
End Cover	135 D01 504-1 135D015041	MTU 839	6	New
Wheel Case Cover, Left-Hand	135 D08 506-1 135D085061	MTU 839	1	New
Valve Gear Pump Shaft	135 E03 707-1 135E037071	MTU 839	1	New
Pump Shaft	135 E03 709-1 135E037091	MTU 839	1	New
Valve	135 F15 700-2 135F157002	MTU 839	5	New
Valve Housing	135 F31 701 135F31701	MTU 839	3	New
Valve Housing	135 F32 701-2 135F327012	MTU 839	3	New
Pressure Relief Valve	135 F40 700-1 135F407001	MTU 839	5	New



Contact	Bank account	Manager & Owner	Chamber of Commerce
Tel: +49 (40) 75 60 59 -0 Fax: +49 (40) 75 95 62 info@metzendorff-co.de TraderNet-ID: 67486	Deutsche Bank AG, Hamburg BIC-No.: DEUTDE33HAN IBAN-No. : DE87 2007 0024 0240 0000 00	Jörn Johannsen Hinrich Warnecke Torben Johannsen	Hamburg registered under A 32 251 VAT-Id.: DE 118 258 306

Description	Part number	Engine	Qty	Condition
Cover	135 F40 703-2 135F407032	MTU 839	4	New
Valve Seat	135 F62 002-1 135F620021	MTU 839	9	New
Pressure Spring, Inner	135 F62 013-1 135F620131	MTU 839	8	New
Valve Plate, small	135 F62 702 135F62702	MTU 839	26	New
Valve Plate	135 F62 712-1 135F627121	MTU 839	10	New
Cover	135 F70 703-2 135F707032	MTU 839	6	New
Housing Lower Part	135 L20 731 135L20731	MTU 839	2	New
Cover	135 L23 702-2 135L237022	MTU 839	3	New
Bearing Flange	135 L42 501-1 135L425011	MTU 839	2	New
Cooler	135 L96 711/1 135L967111	MTU 839	10	Please enquire
Threaded Bush	135 M01 006-1 135M010061	MTU 839	60	New
Supply Line, B-Side	135 M10 007 135M10007	MTU 839	1	New
Supply Line, B-Side	135 M10 007 135M10007	MTU 839	6	Used
Connecting Pipe	135 M12 002-2 135M120022	MTU 839	100	New
Screw	135 M21 003-1 135M210031	MTU 839	6	New
Drive,Fuel Supply Pump	136 L02 700-1 136L027001	MTU 839	5	New
Bearing Flange	136 L42 501-1 136L425011	MTU 839	2	New
Rapid-Action Flap	136 L53 701-2 136L537012	MTU 839	7	New
Shaft	136 L54 049-1 136L540491	MTU 839	4	New
Protective Cap	136 L54 712-1 136L547121	MTU 839	4	New
Support	136 L54 713-1 136L547131	MTU 839	2	Please enquire
Plug	136 L84 002-1 136L840021	MTU 839	12	New
Frame with Strainer	136 L84 706-2 136L847062	MTU 839	2	New
Frame with Strainer	136 L84 707 136L84707	MTU 839	3	New
Bracket	136 L89 741-1 136L897411	MTU 839	6	New



Contact	Bank account	Manager & Owner	Chamber of Commerce
Tel: +49 (40) 75 60 59 -0 Fax: +49 (40) 75 95 62 info@metzendorff-co.de TraderNet-ID: 67486	Deutsche Bank AG, Hamburg BIC-No.: DEUTDE33HAN IBAN-No. : DE87 2007 0024 0240 0000 00	Jörn Johannsen Hinrich Warnecke Torben Johannsen	Hamburg registered under A 32 251 VAT-Id.: DE 118 258 306

Description	Part number	Engine	Qty	Condition
Intermediate Piece	136 L90 007-1 136L900071	MTU 839	23	Please enquire
Spacer Ring	136 L95 004-2 136L950042	MTU 839	12	New
Flange	136 M37 524 136M37524	MTU 839	27	New
Elbow	136 M37 714 136M37714	MTU 839	2	New
Magnet Holder	176 B07 701 176B07701	MTU 839	1	New
Magnet Holder	176 B07 702 176B07702	MTU 839	1	New
Pump Wheel	176 E02 703 176E02703	MTU 839	1	New
Lub Oil Pump	176 E03 702 176E03702	MTU 839	1	New
Gear	176 E03 703 176E03703	MTU 839	1	New
Pump Housing	176 E03 704-1 176E037041	MTU 839	1	New
Shaft	176 E06 701 176E06701	MTU 839	4	Please enquire
Pipe Clamp	176 L55 507 176L55507	MTU 839	10	New
Overflow Pipe	176 L55 508 176L55508	MTU 839	1	New
Pipe Connection	176 L55 509 176L55509	MTU 839	1	New
Pointer	176 L55 515 176L55515	MTU 839	1	New
Spacer	176 L91 702 176L91702	MTU 839	1	New
Piping	176 M19 706 176M19706	MTU 839	2	New
Pipe	176 M27 711 176M27711	MTU 839	1	New
Mounting	177 A09 702 177A09702	MTU 839	10	New
Intermediate Gear	177 A31 701-1 177A317011	MTU 839	2	New
Cover	177 A47 008-1 177A470081	MTU 839	7	New
End Cover	177 A47 010-1 177A470101	MTU 839	2	New
Cover	177 A47 504-1 177A475041	MTU 839	4	New
Drive Shaft	177 E01 703-1 177E017031	MTU 839	10	New
Bearing Bracket	177 E07 702-1 177E077021	MTU 839	3	New

Description	Part number	Engine	Qty	Condition
Stud	177 E16 006-1 177E160061	MTU 839	3	New
Bracket	177 L31 001 177L31001	MTU 839	2	New
Bracket	177 L31 501-1 177L315011	MTU 839	10	New
Intermediate Piece	177 L43 701-1 177L437011	MTU 839	9	New
Gear	197 A29 011 197A29011	MTU 839	1	New
Position Pointer	197 A47 001 197A47001	MTU 839	1	New
Circulation Pump	197 E01 702 197E01702	MTU 839	1	New
Pump Shaft	197 E02 713 197E02713	MTU 839	3	New
Lever	197 L54 704 197L54704	MTU 839	3	New
Retaining Plate	197 L54 731 197L54731	MTU 839	1	Please enquire
Housing	197 L55 501 197L55501	MTU 839	1	New
Oil Guide Ring	302 G28 703-1 302G287031	MTU 839	3	New
Necked-Down Bolt	302 K01 003-1 302K010031	MTU 839	51	New
Retaining Ring	302 K03 004-1 302K030041	MTU 839	5	New
Retaining Ring	302 K03 006-1 302K030061	MTU 839	6	New
Retaining Ring	302 K03 007-1 302K030071	MTU 839	2	New
Grinding Cone	302 K03 026-1 302K030261	MTU 839	10	New
Piston	302 K06 501 302K06501	MTU 839	4	New
Bearing Ring	302 K07 001-1 302K070011	MTU 839	4	New
Necked-Down Bolt	302 K07 008-1 302K070081	MTU 839	40	Please enquire
Spacer Ring	302 K07 009-1 302K070091	MTU 839	3	New
Valve Housing	302 L32 001-1 302L320011	MTU 839	1	New
Valve Guide	302 L32 002-1 302L320021	MTU 839	3	New
Shaft	302 P10 003-1 302P100031	MTU 839	2	New
Pump Housing	302 P10 701 302P10701	MTU 839	3	New



Contact	Bank account	Manager & Owner	Chamber of Commerce
Tel: +49 (40) 75 60 59 -0 Fax: +49 (40) 75 95 62 info@metzendorff-co.de TraderNet-ID: 67486	Deutsche Bank AG, Hamburg BIC-No.: DEUTDE33HAN IBAN-No.: DE87 2007 0024 0240 0000 00	Jörn Johannsen Hinrich Warnecke Torben Johannsen	Hamburg registered under A 32 251 VAT-Id.: DE 118 258 306

Description	Part number	Engine	Qty	Condition
Gear - Oil Pump	302 P12 002-2 302P120022	MTU 839	2	New
Pressure Spring	302 S06 010-1 302S060101	MTU 839	3	New
Piston	302 S06 011-1 302S060111	MTU 839	1	New
Spring Seat	302 S06 012-1 302S060121	MTU 839	2	New
Slide	302 S51 002-1 302S510021	MTU 839	12	New
Guide Rod	302 S51 004-1 302S510041	MTU 839	6	New
Washer	302 S51 005-1 302S510051	MTU 839	6	New
Housing	302 S51 501 302S51501	MTU 839	1	New
Bush	302 S52 002-1 302S520021	MTU 839	3	New
Slide	302 S52 004-1 302S520041	MTU 839	3	New
Slide	302 S52 005-1 302S520051	MTU 839	4	New
Slide	302 S52 006-1 302S520061	MTU 839	3	New
Lock Washer	302 S52 007-1 302S520071	MTU 839	8	New
Flange	302 T19 501-1 302T195011	MTU 839	2	New
Bearing Bush	302 T19 702-1 302T197021	MTU 839	3	New
Bracket	302 T21 002-2 302T210022	MTU 839	2	New
Gear, No. 5	302 T23 001-3 302T230013	MTU 839	2	Please enquire
Grinding Cone	302 T24 004-1 302T240041	MTU 839	28	New
Washer	302 T24 005-1 302T240051	MTU 839	24	New
Intermediate Washer	302 T24 006-1 302T240061	MTU 839	5	New
Centering Cover	302 T24 702-1 302T247021	MTU 839	3	New
Plate	303 G24 701 303G24701	MTU 839	1	New
Disc Piston	303 K02 003 303K02003	MTU 839	1	New
Oil Transfer Pipe	304 K03 702-1 304K037021	MTU 839	6	New
Bush	306 G02 002-1 306G020021	MTU 839	4	New



Contact	Bank account	Manager & Owner	Chamber of Commerce
Tel: +49 (40) 75 60 59 -0 Fax: +49 (40) 75 95 62 info@metzendorff-co.de TraderNet-ID: 67486	Deutsche Bank AG, Hamburg BIC-No.: DEUTDE33HAN IBAN-No.: DE87 2007 0024 0240 0000 00	Jörn Johannsen Hinrich Warnecke Torben Johannsen	Hamburg registered under A 32 251 VAT-Id.: DE 118 258 306

Description	Part number	Engine	Qty	Condition
Bush	306 G02 003-1 306G020031	MTU 839	5	New
Bush	306 G02 702-1 306G027021	MTU 839	4	New
Bush	306 G10 001-1 306G100011	MTU 839	4	New
Flange	306 G25 504 306G25504	MTU 839	1	New
Gasket	306 G28 006-1 306G280061	MTU 839	16	New
Gear, No. 14	306 K03 004-1 306K030041	MTU 839	2	New
Union	306 L23 017 306L23017	MTU 839	2	New
Toothed Ring	375 333 375333	MTU 839	3	New
Eccentric Bush	397 G02 003 397G02003	MTU 839	2	New
Bush	397 G10 001 397G10001	MTU 839	1	New
Oil Line	397 G28 703 397G28703	MTU 839	2	New
Valve Housing	397 S06 702 397S06702	MTU 839	3	Please enquire
Double Ball Joint	501 581 725 501581725	MTU 839	20	New
Ball Socket	511 580 716 511580716	MTU 839	10	New
Protective Cap	514 H03 001-1 514H030011	MTU 839	12	New
Carrier	514 H20 701-1 514H207011	MTU 839	4	New
Shaft	514 M10 001-1 514M100011	MTU 839	3	New
Shaft	514 M10 002-2 514M100022	MTU 839	3	New
Spring Abutment	514 M10 705-1 514M107051	MTU 839	2	New
Damper Washer	518 430 010 518430010	MTU 839	109	New
Carrier	524 H20 501-1 524H205011	MTU 839	3	New
Packing	524 H22 003-1 524H220031	MTU 839	4	New
Carrier	524 H22 702-1 524H227021	MTU 839	3	New
Carrier	524 L02 003-1 524L020031	MTU 839	15	New
Flange	535 E03 002-2 535E030022	MTU 839	2	New



Contact	Bank account	Manager & Owner	Chamber of Commerce
Tel: +49 (40) 75 60 59 -0 Fax: +49 (40) 75 95 62 info@metzendorff-co.de TraderNet-ID: 67486	Deutsche Bank AG, Hamburg BIC-No.: DEUTDE33HAN IBAN-No.: DE87 2007 0024 0240 0000 00	Jörn Johannsen Hinrich Warnecke Torben Johannsen	Hamburg registered under A 32 251 VAT-Id.: DE 118 258 306

Description	Part number	Engine	Qty	Condition
Flanged Union	536 D14 763-1 536D147631	MTU 839	4	New
Flap	536 D15 001-1 536D150011	MTU 839	7	New
Pin	536 D15 002-1 536D150021	MTU 839	8	New
Pipe Clamp Half	536 D22 005 536D22005	MTU 839	4	New
Shear Bolt	536 G05 004-1 536G050041	MTU 839	25	New
Support	536 H13 004 536H13004	MTU 839	5	Please enquire
Pipe Clamp Half	536 H13 005-1 536H130051	MTU 839	13	New
Pipe	536 H20 003 536H20003	MTU 839	6	New
Stop Plate	536 H20 013-1 536H200131	MTU 839	8	New
Shaft	536 M08 702-1 536M087021	MTU 839	3	New
Retaining Bracket	576 D18 005 576D18005	MTU 839	1	New
Pin	576 M08 006 576M08006	MTU 839	12	New
Control Panel	576 M08 701 576M08701	MTU 839	3	New
Spacer Tube	576 M09 007 576M09007	MTU 839	2	New
Intermediate Piece	576 M09 502-1 576M095021	MTU 839	2	New
Bracket	576 M09 503 576M09503	MTU 839	1	New
Bracket	576 M09 707 576M09707	MTU 839	1	New
Retaining Plate	576 M12 013 576M12013	MTU 839	2	New
Pressure Valve	577 B06 701 577B06701	MTU 839	1	New
Flange Connector	577 D14 731-1 577D147311	MTU 839	3	New
Bracket	577 H22 501-1 577H225011	MTU 839	4	New
Gasket	577 H23 045 577H23045	MTU 839	11	New
Hand Wheel	577 M08 502-1 577M085021	MTU 839	3	New
Flange Ring	577 M08 503-1 577M085031	MTU 839	3	New
Console	577 M08 703-1 577M087031	MTU 839	5	New



Contact	Bank account	Manager & Owner	Chamber of Commerce
Tel: +49 (40) 75 60 59 -0 Fax: +49 (40) 75 95 62 info@metzendorff-co.de TraderNet-ID: 67486	Deutsche Bank AG, Hamburg BIC-No.: DEUTDE33HAN IBAN-No.: DE87 2007 0024 0240 0000 00	Jörn Johannsen Hinrich Warnecke Torben Johannsen	Hamburg registered under A 32 251 VAT-Id.: DE 118 258 306

Description	Part number	Engine	Qty	Condition
Rod	577 M09 015-2 577M090152	MTU 839	2	New
Thrust spring	577 M09 016-1 577M090161	MTU 839	2	New
Shaft	577 M09 701-1 577M097011	MTU 839	6	Please enquire
Trunnion	577 M10 005-1 577M100051	MTU 839	2	New
Console	577 M10 713-1 577M107131	MTU 839	5	New
Filter	635 B03 701 635B03701	MTU 839	1	New
End Plate	711 A01 037-1 711A010371	MTU 839	3	New
End Plate	711 A01 038-1 711A010381	MTU 839	3	New
Lock Washer	711 A02 026-1 711A020261	MTU 839	2	New
Spring	711 A03 003-1 711A030031	MTU 839	1	New
Pin	711 A03 009-1 711A030091	MTU 839	3	New
Lever	711 A03 503-1 711A035031	MTU 839	4	New
Cover	711 A03 506-1 711A035061	MTU 839	3	New
Cover	711 A03 702-1 711A037021	MTU 839	4	New
Spring	711 A05 002-1 711A050021	MTU 839	3	New
Cover	711 A05 504-1 711A055041	MTU 839	3	New
Adjusting Washer	711 A05 901-1 711A059011	MTU 839	2	New
Spring, Outer	711 A06 018-1 711A060181	MTU 12V 839	4	Please enquire
Spring, Inner	711 A06 019-1 711A060191	MTU 12V 839	4	New
Intermediate Piece	711 A06 501-1 711A065011	MTU 839	5	New
End Cover	711 A06 508-1 711A065081	MTU 839	4	New
Distance Ring, S=2,7	711 C08 306-1 711C083061	MTU 839	45	New
Distnace Ring, S=2.3	711 C08 308-1 711C083081	MTU 839	20	New
Distance Ring, S=1,9	711 C08 310-1 711C083101	MTU 839	22	New
Distance Ring, S=1,5	711 C08 312-1 711C083121	MTU 839	3	New



Contact	Bank account	Manager & Owner	Chamber of Commerce
Tel: +49 (40) 75 60 59 -0 Fax: +49 (40) 75 95 62 info@metzendorff-co.de TraderNet-ID: 67486	Deutsche Bank AG, Hamburg BIC-No.: DEUTDE33HAN IBAN-No. : DE87 2007 0024 0240 0000 00	Jörn Johannsen Hinrich Warnecke Torben Johannsen	Hamburg registered under A 32 251 VAT-Id.: DE 118 258 306

Description	Part number	Engine	Qty	Condition
Distance Ring, S=1,3	711 C08 313-1 711C083131	MTU 839	31	New
Spacer Ring	711 D02 041-1 711D020411	MTU 839	5	New
Threaded Pin	711 D04 006 711D04006	MTU 839	18	New
Piston Housing	711 D05 501-4 711D055014	MTU 839	4	New
Diaphragm Spring	711 D08 312-1 711D083121	MTU 839	2	New
Bush	711 E02 013-1 711E020131	MTU 839	7	New
Threaded Pin	711 E02 054-1 711E020541	MTU 839	13	New
Transmission Lever	711 E02 710 711E02710	MTU 839	1	New
Transmission Lever	711 E02 720-1 711E027201	MTU 839	9	New
Ratchet	711 E04 504-1 711E045041	MTU 839	4	New
Cover	711 E04 507-1 711E045071	MTU 839	3	New
Spring Seat	711 F02 030-1 711F020301	MTU 839	3	New
Governor Spring	711 F82 008-2 711F820082	MTU 839	4	New
Regulator Pendulum	712 A01 756-2 712A017562	MTU 839	6	New
Spacer Tube	712 A06 023-1 712A060231	MTU 839	8	New
Spacer Ring	712 E08 901-1 712E089011	MTU 839	5	New
Lub Oil Pump	713 A01 706 713A01706	MTU 839	1	New
Threaded Bush	716 E01 001-1 716E010011	MTU 839	4	New
Bush	716 E02 019-1 716E020191	MTU 839	3	New
Bush	716 E02 020-1 716E020201	MTU 839	6	New
Pressure Bush	716 E02 021-1 716E020211	MTU 839	6	New
Pin	716 E02 022-1 716E020221	MTU 839	5	New
Spring Seat	716 E02 025-1 716E020251	MTU 839	4	New
Adjusting Screw	716 E02 028-1 716E020281	MTU 839	5	New
Thrust Pin	716 E02 029-1 716E020291	MTU 839	4	New



Contact	Bank account	Manager & Owner	Chamber of Commerce
Tel: +49 (40) 75 60 59 -0 Fax: +49 (40) 75 95 62 info@metzendorff-co.de TraderNet-ID: 67486	Deutsche Bank AG, Hamburg BIC-No.: DEUTDE33HAN IBAN-No.: DE87 2007 0024 0240 0000 00	Jörn Johannsen Hinrich Warnecke Torben Johannsen	Hamburg registered under A 32 251 VAT-Id.: DE 118 258 306

Description	Part number	Engine	Qty	Condition
Guide Piece	716 E02 049-2 716E020492	MTU 839	6	New
Pressure Spring	716 E02 055-3 716E020553	MTU 839	5	New
Transmission Lever	716 E02 509-1 716E025091	MTU 839	4	New
Cover	716 E02 510-1 716E025101	MTU 839	2	New
Guide Lever	716 E02 515-3 716E025153	MTU 839	3	New
Pin	716 E04 004-1 716E040041	MTU 839	5	New
Roller	716 E04 005-1 716E040051	MTU 839	13	New
Bracket	716 E04 701-1 716E047011	MTU 839	6	New
Governor Housing	716 F01 711-2 716F017112	MTU 839	1	New
Spring Seat Upper	716 F05 007-1 716F050071	MTU 12V 839	4	New
Control Piston	716 F05 010-1 716F050101	MTU 839	5	New
Bush	716 F08 301-1 716F083011	MTU 839	3	New
Pressure Bush	716 F08 791-1 716F087911	MTU 839	3	New
Connecting Rod	724 A06 703 724A06703	MTU 839	1	New
Castle Nut	738 E18 303 738E18303	MTU 839	6	New
Bush	752 B02 002-1 752B020021	MTU 839	14	New
Spacer Bush	752 C04 094-1 752C040941	MTU 839	3	New
Lever	752 C04 510-1 752C045101	MTU 839	4	New
Housing	752 C04 701 752C04701	MTU 839	3	New
Bolt	752 C05 510 752C05510	MTU 839	6	New
Transmitting Shaft	752 C06 001-1 752C060011	MTU 839	3	New
Adjusting Nut	752 C06 011-1 752C060111	MTU 839	3	New
Bush	762 S11 006-2 762S110062	MTU 839	3	New
Rack	797 A02 057 797A02057	MTU 839	3	New
Propeller Shaft	797 A02 058 797A02058	MTU 839	2	New



Contact	Bank account	Manager & Owner	Chamber of Commerce
Tel: +49 (40) 75 60 59 -0 Fax: +49 (40) 75 95 62 info@metzendorff-co.de TraderNet-ID: 67486	Deutsche Bank AG, Hamburg BIC-No.: DEUTDE33HAN IBAN-No.: DE87 2007 0024 0240 0000 00	Jörn Johannsen Hinrich Warnecke Torben Johannsen	Hamburg registered under A 32 251 VAT-Id.: DE 118 258 306

Description	Part number	Engine	Qty	Condition
Bush	797 A05 002 797A05002	MTU 839	1	New
Housing	797 A05 701 797A05701	MTU 839	3	New
Slide	797 B02 023 797B02023	MTU 839	11	New
Spring	797 B02 036 797B02036	MTU 839	3	New
Cover	797 B02 711 797B02711	MTU 839	3	New
Piston	797 B03 002 797B03002	MTU 839	6	New
Adjusting Lever	797 B06 016 797B06016	MTU 839	6	New
Filling Ring	804 A09 004-1 804A090041	MTU 839	8	New
Blade Diffusor	804 C10 502-1 804C105021	MTU 839	3	New
Cover	805 A14 701 805A14701	MTU 839	1	New
Inner Race	805 A25 502 805A25502	MTU 839	2	New
Intermediate Washer	805 B05 012 805B05012	MTU 839	2	New
Intermediate Washer	805 B05 013 805B05013	MTU 839	2	New
Intermediate Washer	805 B05 015 805B05015	MTU 839	2	New
Flange Ring	805 B05 502-1 805B055021	MTU 839	1	New
Flange	805 B05 503-1 805B055031	MTU 839	1	New
Multipiece Oil Ring	805 B11 001-1 805B110011	MTU 839	3	New
Conical Bush	805 B11 002-1 805B110021	MTU 839	2	New
Spacer Ring	805 B11 007-1 805B110071	MTU 839	3	New
Oil Screw	805 C01 001-1 805C010011	MTU 839	4	New
Diffusor, complete	805 C01 701-2 805C017012	MTU 839	1	New
Oil Drip Pipe	805 C01 703 805C01703	MTU 839	1	New
Valve Housing	806 A18 702-1 806A187021	MTU 839	5	New
Inner Race	806 A23 503-1 806A235031	MTU 839	28	New
Outer Race	806 A23 512-3 806A235123	MTU 839	17	New



Contact	Bank account	Manager & Owner	Chamber of Commerce
Tel: +49 (40) 75 60 59 -0 Fax: +49 (40) 75 95 62 info@metzendorff-co.de TraderNet-ID: 67486	Deutsche Bank AG, Hamburg BIC-No.: DEUTDE33HAN IBAN-No.: DE87 2007 0024 0240 0000 00	Jörn Johannsen Hinrich Warnecke Torben Johannsen	Hamburg registered under A 32 251 VAT-Id.: DE 118 258 306

Description	Part number	Engine	Qty	Condition
Intermediate Plate	820 181 1322 8201811322	MTU 839	20	New
Big End Bearing	835 030 3360 8350303360	MTU 839	48	New
Bearing Bush	837 055 0150 8370550150	MTU 839	50	New
Adapter	839 010 0670 8390100670	MTU 839	2	New
Valve Housing	839 010 0990 8390100990	MTU 839	8	New
Cover	839 011 0133 8390110133	MTU 839	10	New
Spring	839 011 3001 8390113001	MTU 839	16	New
Cover	839 015 0403 8390150403	MTU 839	2	New
Bolt	839 016 0669 8390160669	MTU 839	36	New
Main Bearing	839 030 0041 8390300041	MTU 839	17	New
Thrust Bearing	839 030 2146 8390302146	MTU 839	5	New
Thrust Bearing	839 030 3146 8390303146	MTU 839	5	New
Flange Ring	839 031 0133 8390310133	MTU 839	1	New
Piston Pin	839 037 0020 8390370020	MTU 839	13	New
Rocker Shaft	839 050 0031 8390500031	MTU 839	6	New
Rocker Shaft	839 050 0131 8390500131	MTU 839	24	New
Gear	839 050 1305 8390501305	MTU 839	2	New
Gear	839 050 1405 8390501405	MTU 839	2	New
Carrier	839 060 0130 8390600130	MTU 839	5	New
Governor	839 060 0161 8390600161	MTU 839	1	New
Carrier	839 060 0441 8390600441	MTU 839	3	New
Housing	839 070 0015 8390700015	MTU 839	2	New
Carrier	839 070 0424 8390700424	MTU 839	1	New
Drive	839 070 1145 8390701145	MTU 839	2	New
Carrier	839 075 0140 8390750140	MTU 839	4	New



Contact	Bank account	Manager & Owner	Chamber of Commerce
Tel: +49 (40) 75 60 59 -0 Fax: +49 (40) 75 95 62 info@metzendorff-co.de TraderNet-ID: 67486	Deutsche Bank AG, Hamburg BIC-No.: DEUTDE33HAN IBAN-No.: DE87 2007 0024 0240 0000 00	Jörn Johannsen Hinrich Warnecke Torben Johannsen	Hamburg registered under A 32 251 VAT-Id.: DE 118 258 306

Description	Part number	Engine	Qty	Condition
Bracket	839 075 0340 8390750340	MTU 839	2	New
Bracket	839 075 0440 8390750440	MTU 839	4	New
Cover	839 076 0130 8390760130	MTU 839	4	New
Adjusting Lever	839 153 0139 8391530139	MTU 839	3	New
Carrier	839 170 0539 8391700539	MTU 839	1	New
Continuation	839 172 0171 8391720171	MTU 839	34	New
Washer	839 175 3452 8391753452	MTU 839	10	New
Auxiliary Shaft	839 180 0208 8391800208	MTU 839	2	New
Bracket	839 180 1140 8391801140	MTU 839	4	New
Valve Guide	839 181 0044 8391810044	MTU 839	6	New
Protective Cap	839 200 0133 8392000133	MTU 839	4	New
Bracket	839 200 0140 8392000140	MTU 839	3	New
Carrier	839 200 0839 8392000839	MTU 839	1	New
Cap Nut	839 990 0053 8399900053	MTU 839	4	New
Pull Rod	839 996 0925 8399960925	MTU 839	3	New
Thread Feed	839 997 1315 8399971315	MTU 839	11	New
Threaded Union	839 997 1372 8399971372	MTU 839	16	New
Threaded Union	839 997 1672 8399971672	MTU 839	4	New
Threaded Union	839 997 1772 8399971772	MTU 839	9	New
Mechanical Seal, with Counter Ring	849 586 0077 8495860077	MTU 839	2	New
Guide Ring	897 A25 501 897A25501	MTU 839	1	New
Washer	897 B05 013 897B05013	MTU 839	6	New